



DET NORSKE VERITAS

MANAGEMENT SYSTEM CERTIFICATE

Certificate No.: 85145-2010-AHSO-CZS-RvA
1/2

This is to certify that the Management System of:

ŠKODA JS a.s.

Orlík 266, 316 06 Plzeň, Czech Republic

has been found to conform to:

OHSAS 18001:2007

This Certificate is valid for the following product or service ranges:

Design, manufacture and installation of nuclear systems and components. Technical services for nuclear power plants. Design, manufacture, installation, examinations and testing of heat exchangers, tanks, boilers, pressure vessels and heavy welded constructions. Manufacture of aerospace parts and components.

Initial Certification date:

31 July 2008

Place and date:

Prague, 24 September 2010

This Certificate is valid until:

31 July 2013

for the Accredited Unit:

DET NORSKE VERITAS CERTIFICATION B.V.,
THE NETHERLANDS

The audit has been performed under the supervision of

Juraj Kramara
Lead Auditor



Tomáš Urban
Management Representative

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.



DET NORSKE VERITAS

APPENDIX TO CERTIFICATE

This Appendix refers to Certificate No. 85145-2010-AHSO-CZS-RvA
2/2

ŠKODA JS a.s.

locations included in the certification are as follows:

ŠKODA JS a.s., Orlík 266, 316 06 Plzeň, Czech Republic

ŠKODA JS a.s., reaktorová hala, Plzeň - Město, 366 01 Plzeň, Czech Republic

ŠKODA JS a.s. Montážní a servisní středisko Dukovany,
Jaderná Elektrárna Dukovany, 675 50 Dukovany, Czech Republic

ŠKODA JS a.s. Servisní středisko Temelín,
Jaderná Elektrárna Temelín, 373 05 Temelín, Czech Republic

Initial Certification date:

31 July 2008

This Certificate is valid until:

31 July 2013

*The audit has been performed under the
supervision of*

Juraj Kramara
Lead Auditor



Place and date:

Prague, 24 September 2010

for the Accredited Unit:
DET NORSKE VERITAS CERTIFICATION B.V.,
THE NETHERLANDS

Tomáš Urban
Management Representative

Lack of fulfilment of conditions as set out in the Certification Agreement may render this Certificate invalid.